

GC Home Inspection



Residential • Multi-Family • Condos • Townhouses

GC Home Inspection

Phone: 281-682-9558

Email: chadlangston@me.com

Visit us on the web: gchomeinspection.com

2806 Mezzomonte Ln
League City, TX 77573



PROPERTY INSPECTION REPORT

Prepared For: Darrin Haygood
(Name of Client)

Concerning: 2806 Mezzomonte Ln, League City, TX 77573
(Address or Other Identification of Inspected Property)

By: Chad Langston, Lic #7946 04/13/2019
(Name and License Number of Inspector) (Date)

(Name, License Number of Sponsoring Inspector)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous

or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

A. Foundations

Type of Foundation(s): Slab on grade

Comments:

It is the opinion of the inspector that the foundation was performing as intended at the time of inspection.

B. Grading and Drainage

Comments:

The downspout(s) should discharge water at least five (5) feet from the house. Storm water should be encouraged to flow away from the building at the point of discharge.



C. Roof Covering Materials

Types of Roof Covering: Asphalt Shingles

Viewed From: Walked on roof

Comments:

Tree branches too close to the home can damage the structure. Repairs should be made.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



D. Roof Structures and Attics

Viewed From: Entered attic and performed visual inspection

Approximate Average Depth of Insulation: 12 inches

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

E. Walls (Interior and Exterior)

Comments:

The joints in the Hardie plank should be better sealed. More information can be obtained at:

http://www.jameshardie.com/builder/products_siding_hardieplankLapSiding.py?openTab=jsnavLink4

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Damage to the exterior siding on the south side of the home was observed and should be repaired as necessary.



Exterior wall penetrations should be examined and sealed as necessary.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



F. Ceilings and Floors

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

G. Doors (Interior and Exterior)

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

H. Windows

Comments:

Damaged screen(s) were found on the window(s) should be repaired or replaced.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Damage was noted on the window sill in the west bedroom. Repairs should be made as necessary.



I. Stairways (Interior and Exterior)

Comments:

The bottom side of the stairs should be fire stopped.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



-

J. Fireplaces and Chimneys

Comments:

-

K. Porches, Balconies, Decks, and Carports

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

II. ELECTRICAL SYSTEMS

-

A. Service Entrance and Panels

Comments:

In accordance with the Texas Real Estate Commission, Chapter 535 §535.229 (a)(17), states that “the lack of arc-fault circuit interrupting devices serving family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, or similar rooms or areas; and failure of operation of installed arc-fault circuit interrupter devices” shall be reported as Deficient.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

B. Branch Circuits, Connected Devices, and Fixtures

Type of Wiring: Copper

Comments:

Missing globes for light fixtures at the rear of the home should be replaced.

Missing outlet cover plates in the kitchen should be replaced.



The light is inoperative in the second floor bathroom (above tub). If the bulbs are not blown, the circuit should be investigated.

The installation of a ground fault circuit interrupter (GFCI) is recommended in the kitchen at all counter top level and islands. A ground fault circuit interrupter (GFCI) offers protection from shock or electrocution.

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

-

A. Heating Equipment

Type of Systems: Central

Energy Sources: Gas

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

B. Cooling Equipment

Type of Systems: Central
Comments:

Model# - CA16NA048-A
S/N - 1812E13722

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

-

C. Duct Systems, Chases, and Vents

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

IV. PLUMBING SYSTEMS

-

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Southwest corner of the lot
Location of main water supply valve: Southwest corner of the home
Static water pressure reading: 55 psi
Comments:

Water lines exposed on the exterior should be insulated to protect the pipe from damage during freezing temperatures.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

The sink in the second floor bathroom (sink on left) was observed to drain slowly, suggesting that an obstruction may exist.

B. Drains, Wastes, and Vents

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

C. Water Heating Equipment

Energy Sources: Gas

Capacity: 40 Gallon

Comments:

The temperature of the water was found to be in excess of 120 degrees Fahrenheit. Water temperatures of 140 degrees Fahrenheit can cause full thickness third degree burns in as little as 5 seconds. The temperature recorded today was 152.2 F.

D. Hydro-Massage Therapy Equipment

Comments:

V. APPLIANCES

A. Dishwashers

Comments:

Model# - KDTE254ESS2

S/N - F64326637

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

B. Food Waste Disposers

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

C. Range Hood and Exhaust Systems

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

D. Ranges, Cooktops, and Ovens

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

E. Microwave Ovens

Comments:

Model# - NOKCMS2255BSS1
S/N - XV70700136

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

F. Mechanical Exhaust Vents and Bathroom Heaters

Comments:

It is the opinion of the inspector that this system was functioning as intended at the time of inspection. No significant deficiencies were observed.

G. Garage Door Operators

Comments:

When a garage door is equipped with an automatic opener, the locking mechanism should be disabled or removed.

H. Dryer Exhaust Systems

Comments:

The dryer vent should be further inspected and cleaned as necessary.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
----------	-----------	-----------	----------



Summary

Repair Items

The downspout(s) should discharge water at least five (5) feet from the house. Storm water should be encouraged to flow away from the building at the point of discharge.

Tree branches too close to the home can damage the structure. Repairs should be made.

The joints in the Hardie plank should be better sealed. More information can be obtained at:

http://www.jameshardie.com/builder/products_siding_hardieplankLapSiding.py?openTab=jsnavLink4

Damage to the exterior siding on the south side of the home was observed and should be repaired as necessary.

Exterior wall penetrations should be examined and sealed as necessary.

Damaged screen(s) were found on the window(s) should be repaired or replaced.

Damage was noted on the window sill in the west bedroom. Repairs should be made as necessary.

The bottom side of the stairs should be fire stopped.

Missing globes for light fixtures at the rear of the home should be replaced.

Missing outlet cover plates in the kitchen should be replaced.

The light is inoperative in the second floor bathroom (above tub). If the bulbs are not blown, the circuit should be investigated.

The installation of a ground fault circuit interrupter (GFCI) is recommended in the kitchen at all counter top level and islands. A ground fault circuit interrupter (GFCI) offers protection from shock or electrocution.

Water lines exposed on the exterior should be insulated to protect the pipe from damage during freezing temperatures.

The sink in the second floor bathroom (sink on left) was observed to drain slowly, suggesting that an obstruction may exist.

The temperature of the water was found to be in excess of 120 degrees Fahrenheit. Water temperatures of 140 degrees Fahrenheit can cause full thickness third degree burns in as little as 5 seconds. The temperature recorded today was 152.2 F.

When a garage door is equipped with an automatic opener, the locking mechanism should be disabled or removed.

The dryer vent should be further inspected and cleaned as necessary.